

NPI MISSOURI INC

636-940-1005 rgould@npimo.com http://www.npimo.com



RESIDENTIAL REPORT

26442 Highway 49 Lesterville, MO 63654

> Jason Wallingford 12/04/2025



Inspector
Robert Gould
ASHI #205896, Qualified MO Septic
Inspector #50581
636-940-1005
rgould@npimo.com



Agent
Jason Wallingford
Trophy PA Chesterfield
(314) 882-6971
jasonw@trophypa.com

TABLE OF CONTENTS

1: Inspection Details	5
2: Structural Components	8
3: Exterior	12
4: Roofing	19
5: Electrical	21
6: Plumbing	24
7: Heating	29
8: Air Conditioning	30
9: Interiors	32
10: Built-in Appliances	34
11: Insulation and Ventilation	36
Standards of Practice	38

NPI Missouri Inc Page 2 of 39

SUMMARY





- 2.1.1 Structural Components Foundation, Basement & Crawlspaces: High Moisture Levels
- △ 2.1.2 Structural Components Foundation, Basement & Crawlspaces: Mold
- 2.1.3 Structural Components Foundation, Basement & Crawlspaces: Missing/Damaged Vapor Barrier
- 2.1.4 Structural Components Foundation, Basement & Crawlspaces: Crawlspace Conditions
- 2.2.1 Structural Components Floor Structure: Water Damage
- 3.1.1 Exterior Siding, Flashing & Trim: General Deterioration (wood/composite)
- 3.5.1 Exterior Decks, Balconies, Porches & Steps: General Deterioration
- 3.6.1 Exterior Vegetation, Grading, Drainage & Retaining Walls: Poor drainage
- 3.6.2 Exterior Vegetation, Grading, Drainage & Retaining Walls: Trim Vegetation
- 3.7.1 Exterior Walkways, Patios & Driveways: Unsafe rail openings
- 4.2.1 Roofing Roof Drainage Systems: Clogged/Debris
- 4.3.1 Roofing Flashings: Improper Installation

5.2.1 Electrical - Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels: Panel clearance

Θ

- 5.3.1 Electrical Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage: Improper Wiring
- 5.6.1 Electrical GFCI & AFCI: No GFCI Protection Installed
- 6.2.1 Plumbing Drain, Waste, & Vent Systems: Seepage
- 6.2.2 Plumbing Drain, Waste, & Vent Systems: Improper Installation S-Trap
- 6.3.1 Plumbing Water distribution: Corrosion
- 6.4.1 Plumbing Water Heater: Unit not cycled
- 6.7.1 Plumbing Septic System: Not located
- 8.1.1 Air Conditioning Cooling Equipment: Unit Not Cycled
- ⚠ 9.1.1 Interiors Walls: Visible Mold
- 9.3.1 Interiors Floors: Buckled carpet
- 9.6.1 Interiors Windows: Water intrusion
- 10.1.1 Built-in Appliances Dishwasher: Installation Incomplete

NPI Missouri Inc Page 3 of 39

- 10.4.1 Built-in Appliances Design Life: Beyond Design Life
- 11.1.1 Insulation and Ventilation Attic Insulation: Insufficient
- 11.1.2 Insulation and Ventilation Attic Insulation: Insulation missing

○ 11.3.1 Insulation and Ventilation - Exhaust Systems: No Dryer Vent

NPI Missouri Inc Page 4 of 39

1: INSPECTION DETAILS

Information

Occupied

Vacant

Type of BuildingSingle Family

Style

Ranch

Weather Conditions

Dry, Cloudy, Ground Frozen

Temperature (approximate)

30 Fahrenheit (F)

NPI Missouri Inc Page 5 of 39

Report Info

Home

CATEGORIES:

This report divides deficiencies into three categories; Maintenance Items (colored in BLUE), Recommendations (in ORANGE), and MAJOR CONCERN/SAFETY (in RED).

MAINTENANCE ITEMS: Include components that were found to be in need of recurring or basic general maintenance to protect either a the component or the occupants. Also included in this section are items that were beginning to show signs of wear, but were, in the opinion of the inspector, still functional at the time of inspection. Typically these items are considered to represent a less significant immediate cost than those listed in the following two categories.

RECOMMENDATIONS/REPAIR: Include comments of a deficiency, a latent defect or a suggested improvement of a system which may have appeared functional at the time of inspection, however some benefit may be achieved by adhering to the recommendation.

MAJOR CONCERN/SAFETY: Will denote a brief comment of a significantly deficient component or a condition, which may require a relatively expensive correction and/or replacement or a Safety Item, which may not be severe, but we want you to know its in need of more immediate attention. These will typically fall into one of the following four categories:

- 1. Major defects. An example of this would be a structural failure, roof replacement etc..
- 2. Items costing over \$1000 or for repair/replacement.
- 3. Safety hazards such as an exposed wire, or double taps at main etc...

Anything in these categories should be addressed. Often, a serious problem can be corrected inexpensively to protect both life and property.

This categorization is the opinion of the inspector and is based on what was observed at the time of inspection. It is not intended to imply that items documented in any one category are not in need of correction. Maintenance items or latent defects not repaired in a reasonable amount of time, can soon become significant defects. It should be considered very likely there will be other issues you personally may consider deficient, and you should add these as desired. There may also be defects that you feel belong in a different category, and again, you should feel free to consider the importance you believe they hold and act accordingly.

Please review the report in its entirety. It is ultimately up to your discretion to interpret its findings and to act accordingly. This report does not offer an opinion as to whom among the parties to this transaction should take responsibility for addressing any of these concerns. As with all aspects of your transaction, you should consult with your Realtor® for further advice regarding the contents of this report. Any repairs should be performed by the applicable licensed and bonded tradesman or qualified professional who will provide copies of all receipts, warranties and applicable permits for any repairs that are carried out.

The report lists deficiencies visible at the time of inspection. The inspector is not required to move furniture, appliances, storage, or disassemble components beyond normal user controls nor perform destructive testing. National Property Inspections does not accept responsibility for hidden or latent defects discovered upon occupancy or during remodeling after the date of inspection. Please note that our inspection is thorough but not technically exhaustive. The intent of this inspection is to discover significant defects as it is not possible to detect every maintenance or minor repair item. Most homes continue to be occupied after our inspections, thus we do not warrant 100% discovery of all maintenance or minor repair items such as drippy faucets, isolated wood damage, light switch functionality, etc. We do not inspect for county or municipal code compliance as the St. Louis Metro area and adjacent counties have many jurisdictions, thus codes are interpreted and enforced differently. National Property Inspections has no legal authority to mandate compliance to the municipal codes and ordinances. This report does not list municipal or county code infractions.

Use of Report

Our inspection report is for the use of our client(s). This report is only for the benefit of the person(s) listed on this report unless specifically agreed to otherwise in writing.

The summary section pages are not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your real estate agent or an attorney.

NOT A GUARANTEE

National Property Inspections does not guarantee future performance or provide a warranty, expressed or implied, regarding the inspected property after or during the date of inspection. Warranty policies are readily available for purchase. We are not liable for defects covered by the homeowner's hazard insurance policy or items covered by a warranty program. Should you discover a defect for which you think National Property Inspections may be liable, you must notify us within 24 hours and provide a reasonable opportunity of 2 to 5 business days to reinspect the property before the defect is repaired. If National Property Inspections is not given the opportunity to review an alleged liability, we do not accept any responsibility for the claim. Even properties vacant between the time of inspection and closing can develop mechanical, electrical or plumbing defects. The purchaser's pre-closing final walk through is extremely important to confirm that all systems are operable, that maintenance or repair issues have not developed since the

NPI Missouri Inc Page 6 of 39

inspection and any requested repairs have been completed to your satisfaction. National Property Inspections accepts no responsibility for defects that could have been observed during the final walk through, provided by the St. Louis Association of Realtors Residential Sales Contract.

Information in this report is based on a limited visual examination given the current conditions at the time of the inspection. This information can help you understand the risks of owning this property but it cannot eliminate those risks, nor can it specifically predict future performance. We help you assess these risks; we do not assume them for you.

Code and Environmental Issues Excluded

We do not include inspection for "code" compliance. As contractors make repairs or do maintenance to the home, you should expect the need to update items to meet current code requirements. This may substantially increase cost of the repairs.

We do not include inspection or testing for EPA listed or any other environmental hazards or materials such as asbestos, mold, lead paint, underground storage tank or other environmentally related items, unless ordered and paid for at the time of the inspection.

We do not inspect for termites or other vermin unless ordered and paid for during this inspection.

Photograph Info

Photos are inserted throughout the report and are intended to be used to help further explain the conditions described. The photographs are an example of the condition described and may not show the entire deficiency or all occurrences of the same deficiency.

NPI Missouri Inc Page 7 of 39

2: STRUCTURAL COMPONENTS

		IN	NI	NP	0
2.1	Foundation, Basement & Crawlspaces	Χ			Χ
2.2	Floor Structure	Χ			Χ
2.3	Wall Structure	Χ			
2.4	Roof Structure & Attic	Χ			
2.5	Ceiling Structure	Χ			

NP = Not Present

O = Observations

Information

Foundation, Basement & **Crawlspaces: Foundation** Concrete, Crawl Space

Floor Structure: Sub-floor

Floors Plywood

Roof Structure & Attic: Material

Plywood

Floor Structure:

Basement/Crawlspace Floor

Wall Structure: Material

Wood


Floor Structure: Material

Floor Framing

Dimensional Lumber

Ceiling Structure: Material

Attic Wood



Page 8 of 39 NPI Missouri Inc

Observations

2.1.1 Foundation, Basement & Crawlspaces



HIGH MOISTURE LEVELS

CRAWL SPACE

Evidence of high moisture content is present in the crawl space. Conditions are most like due to poor ventilation and the near level lot condition.

2.1.2 Foundation, Basement & Crawlspaces

A Safety Hazards

MOLD

CRAWL SPACE

Heavy presence of mold is present throughout the crawl space. Conditions are due to the excessively high moisture content. Recommend removal or treatment of all molded materials and eliminating all sources of moisture.

Recommendation

Contact a qualified mold remediation contractor









NPI Missouri Inc Page 9 of 39

2.1.3 Foundation, Basement & Crawlspaces

MISSING/DAMAGED VAPOR BARRIER

CRAWLSPACE

Vapor barrier is not present. Recommend installing vapor barrier.

Recommendation

Contact a handyman or DIY project





2.1.4 Foundation, Basement & Crawlspaces

CRAWLSPACE CONDITIONS

CRAWLSPACE

Industry standards recommend crawlspace be the same conditions as the ambient air in the living area. Current conditions are closed with exterior ambient conditions.


Recommendation

Contact a qualified professional.

2.2.1 Floor Structure

WATER DAMAGE

CRAWL SPACE



Recommendation

Contact a qualified professional.







Recommendations

NPI Missouri Inc Page 10 of 39



NPI Missouri Inc Page 11 of 39

3: EXTERIOR

		IN	NI	NP	0
3.1	Siding, Flashing & Trim	Χ			Χ
3.2	Eaves, Soffits & Fascia	Χ			
3.3	Windows	Χ			
3.4	Exterior Doors	Χ			
3.5	Decks, Balconies, Porches & Steps	Χ			Χ
3.6	Vegetation, Grading, Drainage & Retaining Walls	Χ			Χ
3.7	Walkways, Patios & Driveways	Χ			Χ

Information

Inspection Method

Attic Access, Visual, Crawlspace Access

Decks, Balconies, Porches &

Steps: Material

Wood

Siding, Flashing & Trim: Siding Material

Wood

Windows: Window Type

Thermal, Vinyl, Wood

Decks, Balconies, Porches & Steps:

Deck with Steps, Covered Porch



NPI Missouri Inc Page 12 of 39

Exterior Doors: Exterior Entry Door

Steel





Walkways, Patios & Driveways: Flatwork Material

Concrete, Gravel






Observations

3.1.1 Siding, Flashing & Trim

GENERAL DETERIORATION (WOOD/COMPOSITE)






Recommendation

Contact a qualified professional.



NPI Missouri Inc Page 13 of 39



NPI Missouri Inc Page 14 of 39








3.5.1 Decks, Balconies, Porches & Steps

GENERAL DETERIORATION

FRONT PORCH



Recommendation


Contact a qualified deck contractor.







NPI Missouri Inc Page 15 of 39



NPI Missouri Inc Page 16 of 39



3.6.1 Vegetation, Grading, Drainage & Retaining Walls

Recommendations

POOR DRAINAGE

EXTERIOR

Home is constructed on a level lot that does not allow water to drain away from the foundation. Conditions are resulting in hydrostatic water and excessive condensation in the crawl space.

Recommendation

Contact a handyman or DIY project









3.6.2 Vegetation, Grading, Drainage & Retaining Walls

TRIM VEGETATION

Trim vegetation off and away from the exterior walls.

Recommendation

Contact a handyman or DIY project



NPI Missouri Inc Page 17 of 39





3.7.1 Walkways, Patios & Driveways

UNSAFE RAIL OPENINGS

FRONT PORCH

Unsafe rail openings are present at the exterior steps.

Recommendation

Contact a qualified professional.





Recommendations

NPI Missouri Inc Page 18 of 39

4: ROOFING

		IN	NI	NP	0
4.1	Coverings	Χ			
4.2	Roof Drainage Systems	Χ			Χ
4.3	Flashings	Χ			Χ
4.4	Skylights, Chimneys & Roof Penetrations	Χ			

Information

Inspection Method

Roof

Roof Type/Style

Gable

Roof Drainage Systems: Gutter

MaterialAluminum

Flashings: Material

Metal

Coverings: Material

Metal



Observations

4.2.1 Roof Drainage Systems



CLOGGED/DEBRIS

ROOF

Downspouts are clogged and filled with debris.

Here is a DIY resource for cleaning your gutters.

NPI Missouri Inc Page 19 of 39

Recommendation


Contact a handyman or DIY project



4.3.1 Flashings

IMPROPER INSTALLATION





Recommendation

Contact a qualified roofing professional.







NPI Missouri Inc Page 20 of 39

5: ELECTRICAL

		IN	NI	NP	0
5.1	Service Entrance Conductors	Χ			
5.2	Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels	Χ			Х
5.3	Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage	Χ			Х
5.4	Connected Devices and Fixtures	Χ			
5.5	Polarity and Grounding of Receptacles	Χ			
5.6	GFCI & AFCI	Χ			Χ
5.7	Smoke Detectors		Χ		

IN = Inspected NI = Not Inspected

NP = Not Present

O = Observations

Information

Branch Wire 15 and 20 AMPCopper

Service and Grounding
Equipment, Main Overcurrent
Device, Main and Distribution
Panels: Panel Capacity
200 AMP



Wiring Method Romex

Service and Grounding
Equipment, Main Overcurrent
Device, Main and Distribution
Panels: Panel Locations
Laundry Room

Service Entrance Conductors: Electrical Service Conductors Below Ground, Aluminum

Service and Grounding
Equipment, Main Overcurrent
Device, Main and Distribution
Panels: Panel Type
Circuit Breaker

Limitations

Smoke Detectors

OPERATION

NPI Missouri Inc Page 21 of 39

Recommend all detectors be tested and replaced as required upon occupancy.

Observations

5.2.1 Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels



PANEL CLEARANCE

Insufficient clearance is present at the panel. Panel requires 36" of clearance from top of panel to floor for safety purposes.

Recommendation

Contact a handyman or DIY project





5.3.1 Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage



IMPROPER WIRING

UTILITY ROOM

Improperly run and unsecured wiring is present in the utility room and water heater. Recommend repairs by a qualified electrical contractor for safety purposes.

Recommendation

Contact a qualified electrical contractor.

NPI Missouri Inc Page 22 of 39





5.6.1 GFCI & AFCI

NO GFCI PROTECTION INSTALLED



KITCHEN, BATHROOMS

GFI protection is not present at all required locations. Recommend qualified electrical contractor install GFI protection for safety purposes

Here is a link to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



NPI Missouri Inc Page 23 of 39

6: PLUMBING

		IN	NI	NP	0
6.1	Fixtures / Faucets	Χ			Χ
6.2	Drain, Waste, & Vent Systems	Χ			Χ
6.3	Water distribution	Χ			Χ
6.4	Water Heater	Χ			Χ
6.5	Vents, Flues, & Chimneys	Χ			
6.6	Fuel Storage & Distribution Systems	Χ			
6.7	Septic System	Χ			Χ

Information

FiltersNone

Main Fuel Shut-Off (Location)
Propane Storage Tank, Exterior,
Electrical Panel, Main Level

Main Water Shut-Off Device (Location)
Garage



Material - DistributionCopper

Drain, Waste, & Vent Systems: Material PVC

Water Heater: Power Source Electric **Material - Water Supply**Copper

Water Heater: Capacity 40 40 Gallons Source Well

Water Heater: Location
Basement

NPI Missouri Inc Page 24 of 39

Water Heater: Manufacturer

Reliance





Limitations

General

WATER MAIN WAS OFF

Water was off at the time of the inspection; therefore, plumbing components were visually inspected only.





Observations

6.2.1 Drain, Waste, & Vent Systems

SEEPAGE

KITCHEN



NPI Missouri Inc Page 25 of 39

Evidence of seepage is present at the drain connections. Recommend maintenance to prevent leaking.

Recommendation

Contact a qualified plumbing contractor.







6.2.2 Drain, Waste, & Vent Systems

IMPROPER INSTALLATION - S-TRAP

BATHROOMS, KITCHEN

S-trap configurations observed. Recommend evaluation and repair by a qualified professional.

Recommendation

Contact a qualified plumbing contractor.







NPI Missouri Inc Page 26 of 39

6.3.1 Water distribution

CORROSION

KITCHEN, BATHROOMS



Corrosion is present on the valves and fixtures in several areas. Recommend further evaluation and replacement where necessary to prevent leaking.

Recommendation

Contact a qualified plumbing contractor.









6.4.1 Water Heater

UNIT NOT CYCLED

UTILTY ROOM

Water heater was not cycled due to the water being shut off at the main. Unit was visually inspected only.

Recommendations

6.7.1 Septic System

NOT LOCATED

EXTERIOR

Due to no access to the surface the septic components (tank and drain field) could not be located; therefore, system does not meet minimum state requirements, components could not be sized and conditions could not be determined. Recommend access to the surface be installed over the inlet and

outlet, tank be pumped, and interior components be evaluated.

NPI Missouri Inc Page 27 of 39

Recommendation

Contact a qualified professional.

NPI Missouri Inc Page 28 of 39

7: HEATING

		IN	NI	NP	0
7.1	Heating Equipment	Χ			
7.2	Distribution Systems	Χ			
7.3	Vents, Flues & Chimneys	Χ			

Heating Equipment: Filter Type

Disposable

NP = Not Present

Heating Equipment: Heat Type

Forced Air

O = Observations

Information

Heating Equipment: Energy

Source

Gas

Distribution Systems: Ductwork

Non-insulated

Heating Equipment: Brand

Goodman





Page 29 of 39 NPI Missouri Inc

8: AIR CONDITIONING

		IN	NI	NP	0
8.1	Cooling Equipment	Χ			Χ
8.2	Distribution System	Χ			

Information

Cooling Equipment: Energy

Source/Type

Electric

Cooling Equipment: Brand

Goodman

Distribution System: Configuration

Split









NPI Missouri Inc Page 30 of 39

Observations

8.1.1 Cooling Equipment



UNIT NOT CYCLED

Outside air temperature too low to cycle the unit(s). System(s) was visually inspected only. See separate HVAC report for conditions.

NPI Missouri Inc Page 31 of 39

9: INTERIORS

		IN	NI	NP	0
9.1	Walls	Χ			Χ
9.2	Ceilings	Χ			
9.3	Floors	Χ			Χ
9.4	Countertops & Cabinets	Χ			
9.5	Doors	Χ			
9.6	Windows	Χ			Χ
9.7	Shower Enclosures	Χ			

Information

Walls: Finish MaterialDrywall

Ceilings: Ceiling MaterialDrywall

Countertops & Cabinets:
Cabinetry
Wood

Windows: Window TypeDouble-hung, Thermal, Vinyl

Observations

9.1.1 Walls

VISIBLE MOLD

UTILITY ROOM



Visible mold is present on the drywall and finish materials. Conditions are due high moisture content. Recommend removal and treatment of all molded materials for health and safety purposes. All sources of moisture should be eliminated to prevent further mold issues.

Recommendation

Contact a qualified professional.







9.3.1 Floors

BUCKLED CARPET



NPI Missouri Inc Page 32 of 39

Maintenance or replacement recommended to all buckled carpet to eliminate trip hazards.

Recommendation

Contact a qualified professional.





9.6.1 Windows

WATER INTRUSION

FAMILY ROOM

Evidence of possible water intrusion is present at the window assemblies.

Recommendation

Contact a qualified professional.







NPI Missouri Inc Page 33 of 39

10: BUILT-IN APPLIANCES

		IN	NI	NP	0
10.1	Dishwasher	Χ			Χ
10.2	Range/Oven/Cooktop	Χ			
10.3	Garbage Disposal	Χ			
10.4	Design Life	Χ			Χ

IN = Inspected

NI = Not Inspected

NP = Not Present

O = Observations

Information

Range/Oven/Cooktop: Exhaust

Hood TypeRe-circulate

Range/Oven/Cooktop:

Range/Oven Energy Source

Electric

Observations

10.1.1 Dishwasher

INSTALLATION INCOMPLETE

KITCHEN

Installation has not been completed, components have not been unpacked and unit has not been cycled.

Recommendation

Contact a qualified professional.



10.4.1 Design Life

BEYOND DESIGN LIFE

STOVE

Appliances are beyond design life. Appliances were cycled and operational at inspection.



NPI Missouri Inc Page 34 of 39



NPI Missouri Inc Page 35 of 39

11: INSULATION AND VENTILATION

		IN	NI	NP	0
11.1	Attic Insulation	Χ			Х
11.2	Ventilation	Χ			
11.3	Exhaust Systems	Χ			Χ

NP = Not Present

O = Observations

Information

Dryer Power Source

220 Electric

Ventilation: Ventilation Type Gable Vents, Soffit Vents

Dryer Vent

Metal (Flex), None Found

Exhaust Systems: Exhaust Fans

Fan with Light

Attic Insulation: Insulation Type

Mineral Wool, Loose Fill

Observations

11.1.1 Attic Insulation

INSUFFICIENT

Insulation is matted due to typical settling and foot traffic. Recommend additional insulation for efficiency purposes.

Recommendation

Contact a qualified insulation contractor.







11.1.2 Attic Insulation

INSULATION - MISSING

CRAWL SPACE

Insulation is not present in the crawl space.

Recommendation

Contact a qualified insulation contractor.

NPI Missouri Inc Page 36 of 39

11.3.1 Exhaust Systems



NO DRYER VENT

Dryer did not have visible venting to the exterior at time of inspection. This can cause a reduction in air flow and affect dryer performance. Recommend a qualified HVAC contractor or handyman install venting to the exterior.



NPI Missouri Inc Page 37 of 39

STANDARDS OF PRACTICE

Inspection Details

Structural Components

3. STRUCTURAL COMPONENTS 3.1 The inspector shall: A. inspect structural components including the foundation and framing. B. describe: 1. the methods used to inspect under floor crawlspaces and attics. 2. the foundation. 3. the floor structure. 4. the wall structure. 5. the ceiling structure. 6. the roof structure. 3.2 The inspector is NOT required to: A. provide engineering or architectural services or analysis. B. offer an opinion about the adequacy of structural systems and components. C. enter under floor crawlspace areas that have less than 24 inches of vertical clearance between components and the ground or that have an access opening smaller than 16 inches by 24 inches. D. traverse attic load-bearing components that are concealed by insulation or by other materials.

Exterior

4.1 The inspector shall: A. inspect: 1. wall coverings, flashing, and trim. 2. exterior doors. 3. attached and adjacent decks, balconies, stoops, steps, porches, and their associated railings. 4. eaves, soffits, and fascias where accessible from the ground level. 5. vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building. 6. adjacent and entryway walkways, patios, and driveways. B. describe wall coverings. 4.2 The inspector is NOT required to inspect: A. screening, shutters, awnings, and similar seasonal accessories. B. fences, boundary walls, and similar structures. C. geological and soil conditions. D. recreational facilities. E. outbuildings other than garages and carports. F. seawalls, break-walls, and docks. G. erosion control and earth stabilization measures.

Roofing

5.1 The inspector shall: A. inspect: 1. roofing materials. 2. roof drainage systems. 3. flashing. 4. skylights, chimneys, and roof penetrations. B. describe: 1. roofing materials. 2. methods used to inspect the roofing. 5.2 The inspector is NOT required to inspect: A. antennas. B. interiors of vent systems, uses, and chimneys that are not readily accessible. C. other installed accessories.

Electrical

7.1 The inspector shall: A. inspect: 1. service drop. 2. service entrance conductors, cables, and raceways. 3. service equipment and main disconnects. 4. service grounding. 5. interior components of service panels and subpanels. 6. conductors. 7. overcurrent protection devices. 8. a representative number of installed lighting fixtures, switches, and receptacles. 9. ground fault circuit interrupters and arc fault circuit interrupters. B. describe: 1. amperage rating of the service. 2. location of main disconnect(s) and subpanels. 3. presence or absence of smoke alarms and carbon monoxide alarms. 4. the predominant branch circuit wiring method. 7.2 The inspector is NOT required to: A. inspect: 1. remote control devices. 2. or test smoke and carbon monoxide alarms, security systems, and other signaling and warning devices. 3. low voltage wiring systems and components. 4. ancillary wiring systems and components not a part of the primary electrical power distribution system. 5. solar, geothermal, wind, and other renewable energy systems. B. measure amperage, voltage, and impedance. C. determine the age and type of smoke alarms and carbon monoxide alarms.

Plumbing

6.1 The inspector shall: A. inspect: 1. interior water supply and distribution systems including fixtures and faucets. 2. interior drain, waste, and vent systems including fixtures. 3. water heating equipment and hot water supply systems. 4. vent systems, flues, and chimneys. 5. fuel storage and fuel distribution systems. 6. sewage ejectors, sump pumps, and related piping. B. describe: 1. interior water supply, drain, waste, and vent piping materials. 2. water heating equipment including energy source(s). 3. location of main water and fuel shut-off valves. 6.2 The inspector is NOT required to: A. inspect: 1. clothes washing machine connections. 2. interiors of vent systems, flues, and chimneys that are not readily accessible. 3. wells, well pumps, and water storage related equipment. 4. water conditioning systems. 5. solar, geothermal, and other renewable energy water heating systems. 6. manual and automatic re-extinguishing and sprinkler systems and landscape irrigation systems. 7. septic and other sewage disposal systems. B. determine: 1. whether water supply and sewage disposal are public or private. 2. water quality. 3. the adequacy of combustion air components. C. measure water supply low and pressure, and well water quantity. D. fill shower pans and fixtures to test for leaks.

Heating

8.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. installed heating equipment. 2. vent systems, uses, and chimneys. 3. distribution systems. C. describe: 1. energy source(s). 2. heating systems. 8.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible. 2. heat exchangers. 3. humidifiers and dehumidifiers. 4. electric air cleaning and sanitizing devices. 5. heating systems using ground-source, water-source, solar, and renewable energy technologies. 6. heat-recovery and similar whole-house mechanical ventilation systems. B. determine: 1. heat supply adequacy and distribution balance. 2. the adequacy of combustion air components.

NPI Missouri Inc Page 38 of 39

Air Conditioning

9.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. central and permanently installed cooling equipment. 2. distribution systems. C. describe: 1. energy source(s). 2. cooling systems. 9.2 The inspector is NOT required to: A. inspect electric air cleaning and sanitizing devices. B. determine cooling supply adequacy and distribution balance. C. inspect cooling units that are not permanently installed or that are installed in windows. D. inspect cooling systems using ground source, water source, solar, and renewable energy technologies.

Interiors

10.1 The inspector shall inspect: A. walls, ceilings, and floors. B. steps, stairways, and railings. C. countertops and a representative number of installed cabinets. D. a representative number of doors and windows. E. garage vehicle doors and garage vehicle door operators. F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: A. paint, wallpaper, and other finish treatments. B. floor coverings. C. window treatments. D. coatings on and the hermetic seals between panes of window glass. E. central vacuum systems. F. recreational facilities. G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or confirm the operation of every control and feature of an inspected appliance.

Built-in Appliances

10.1 The inspector shall inspect: F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or con rm the operation of every control and feature of an inspected appliance.

Insulation and Ventilation

11.1 The inspector shall: A. inspect: 1. insulation and vapor retarders in unfinished spaces. 2. ventilation of attics and foundation areas. 3. kitchen, bathroom, laundry, and similar exhaust systems. 4. clothes dryer exhaust systems. B. describe: 1. insulation and vapor retarders in unfinished spaces. 2. absence of insulation in unfinished spaces at conditioned surfaces. 11.2 The inspector is NOT required to disturb insulation.

NPI Missouri Inc Page 39 of 39